

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Vicky S. Miller Environmental Specialist				
OGM	Steve Demczak Environmental Scientist III				

Inspection Report

Permit Number:	C0070039			
Inspection Type:	COMPLETE			
Inspection Date:	Tuesday, May 12, 2009			
Start Date/Time:	5/12/2009 7:00:00 AM			
End Date/Time:	5/12/2009 12:00:00 PM			
Last Inspection:	Tuesday, February 24, 2009			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 70's

InspectionID Report Number: 2006

Types of Operations

Accepted by: jhelfric 5/14/2009

JOHN R. BAZA

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: DUGOUT CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

9,751.00	Total Permitted		
101.10	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Current Acreages

Mineral Ownership

✓ Underground ✓ Federal Surface State Loadout County Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions for the Dugout Canyon Mine permit area.

The Permittee is current relative to the required electronic guarterly water monitoring submittals for 2008.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Wednesday, May 13, 2009

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070039
Inspection Type: COMPLETE

Inspection Date: Tuesday, May 12, 2009

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	V		~	
3.	Topsoil	✓		~	
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		V	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		~	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation	V			
12.	Backfilling And Grading	✓			
13.	Revegetation	V			
14.	Subsidence Control	V			
15.	Cessation of Operations	✓			
16.8	a Roads: Construction, Maintenance, Surfacing	V			
16.l	Roads: Drainage Controls	V		✓	
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	V		V	
19.	AVS Check	V			
20.	Air Quality Permit	V			
21.	Bonding and Insurance	V		V	
22.	Other				

Permit Number: C0070039
Inspection Type: COMPLETE

Inspection Date: Tuesday, May 12, 2009

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

DOGM Permit will expire on March 17, 2013. This permit was renewed on October 10, 2008. The permit was signed by the Director of DOGM. The UPDES Permit will expire on Nov. 30, 2009. The SPCC plan was reviewed by a P.E. on March 14, 2008.

2. Signs and Markers

The permit sign is located at the gate to the property. Information meets the minimium requirements of the R645 Coal Rules.

3. Topsoil

The topsoil piles at the waste rock sites was inspected. I did see some grasses strarting to come up from the ground.

4.a Hydrologic Balance: Diversions

The diversions were spot inspected and were functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected for the first quarter of 2009. No hazardous conditions were reported. The sediment pond did contain water but was not discharging during the inspection.

4.d Hydrologic Balance: Water Monitoring

The water information was submitted to the Division for the fourth quarter of 2008.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected and is P.E. certified for the First quarter on March 30, 2009. No hazardous conditions were reported.

8. Noncoal Waste

The mine site was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection.

16.b Roads: Drainage Controls

The permittee has cleaned out the diversions along the road.

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

Permit Number: C0070039

Inspection Type: COMPLETE

Inspection Date: Tuesday, May 12, 2009

Page 4 of 4

21. Bonding and Insurance

The insurance policy will expire on July 31, 2009. The accord form was reviewed and meets the requirements of the R645 Coal Rules. The bonding amount is \$3,550,000. The Reclamation Agreement was inspected and is signed by the Division. The total disturb area is 101.1 acres.